


Southeastern Refractory

A Shotcreting Repair on a Aluminum
35Ton Reverb


Repair Started in Floor



Started Shotcreting Side walls



Side walls are almost completed



Charge Well



Charge Well and hot wall Completed



Shotcreting side walls



Burner Wall Completed



A few final touches



35 ton repair completed

